

This Inflatable Does Not Require Annual Testing

South End, Blackrock, Dundalk, Co. Louth

Directors: Mandy Fee & Shane McBride

Tel: 042-9323529 Mobile: 087 - 2222100 or 087 - 6644442

Email: info@pelican.ie

Structure

	PASS	FAIL	N/A
1 Trough Depth	X		
2 Security Of Seams	x		
3 Stitching	X		
4 Anchor Points	x		
5 Anchor Accessories			X
6 Walls & Towers			X
7 Blower Tube (s)	X		
8 Zips	x		

9 Fabric Flame Retardant	X		
10 Fabric Strength	x		
11 Step/Ramp Size			x
12 Grounding	X		
13 Sharp Angles/Edges	X		
14 Stability	x		
15 Ropes			X
16 Artwork	X		
17 Air Loss Points	x		
18 Water Gauge Pressure			x
19 Fall of Height	x		
20 Thread	X		
21 Netting			x
22 Entrapment	x		
23 Deflation/Evacuation	X		
24 Windows			X
25 Markings	X		
26 Identification	x		

Total Enclosed Structures


27 Exits			X
28 Exit Markings			X
29 Lighting Supports			X
30 Emergency Lighting			X
31 Deflation Speed			X
32 User Area Pressure			X

Slides

33 Wall Heights			X
34 Run Out			X
35 Clamber Step			X
36 Slide Sheet			X

Blower (s)

37 Size & Type			X
38 Inlet & Outlet Mesh Size			X
39 Cable & Plug			X
40 Casing & Impeller			X
41 Pat Test			X
42 Return Flap			X

Certificate Number	N/A			
Date Of Test	01/02/19			
Unit Serial Number	N/A			
Inflatable Type/Picture	<p style="text-align: center;">x</p> 			
Tag Number	N/A			
Annual/Initial	N/A			
Valid From	2019	To	N/A	
Max Use Height	N/A			
Max Number Of Users	Under 1m	1m-1.2m	1.2-1.4m	1.4-1.8m
	N/A	N/A	N/a	N/A
Date Of Manufacture	Unknown			
Manufacturer	Unknown			
Size (ft)	Width	Depth	Height	Platform Height
	15	15	13.6	N/A
Number Of Blowers	1			
Blower Size	1.5HP			
No. Anchor Points	14			
Inside Wall Height (m)	N/A			
Length Of Blower Tube	1.2			
Length Of Ramp (m)	N/A			
Water Gauge Pressure	N/A			
Fall Of Height (m)	N/A			
Risk Assessment If Any				

Signed: _____

Date: _____